

COMPLAINT INVESTIGATION FORMDATE/TIME REPORTED: 6/2/94DISTRICT OFFICE NWDO #1060**COMPLAINANT:**Name: Tom TilsonAddress: Allen Co Emergency ManagementPhone No.: (419) 227-3535*Confidential Status: Y/N

Comments: _____

SUSPECTED SOURCE:Name/Facility: Orbitron IndustriesAddress: 901 S Main StDelphosCounty: ALLEN SUBD 2

Phone No.: _____

Regulatory Status: SQG G T TSD Unreg Cond Ex

USEPA/OHIO ID# _____

STATEMENT OF COMPLAINT: *(Location, type of material, quantity, areas affected, phone #'s)*Three 55-gal drums leaking. Approximately 125 drums on-site (indoors & outdoors).

Contents unknown. DERR on-scene coordinator met w/fire chief @ site 6/2/94. South side
of plant's main bldg found the 3 leaking drums. Black substance from drums had migrated
down across gravel/soil driveway & had soaked into ground. Earthen dike installed around
spilled material. Facility rep contacted. Interdyne contracted for cleanup. Many HW labeled
drums on-site. Some areas contained asbestos. See ER Report.

ASSOCIATED INDIV./COMPANIES: _____

COMPLAINT RECEIVED BY: M Gerber/DERR/NWDO**INVESTIGATION SUMMARY:** *(Use separate summary sheet if handled by district)*

INVESTIGATOR ASSIGNED: _____ PRIORITY: _____

ACTIONS/OBSERVATIONS/RECOMMENDATIONS: _____

INVESTIGATION STATUS/RESOLUTION: _____

OHIO EPA, EMERGENCY RESPONSE GROUP
DISTRICT OFFICE INVESTIGATION REPORTSPILL #: 9406-02-2414 STATUS: F01
DATE SUBMITTED: 06/03/94 ON SCENE COORDINATOR: J.M.Gerber

REPORTED: 0905 06/02/94 DISCOVERED: 0800 06/02/94 OCCURRED: 10/93

REPORTED BY: Tom Tilson PHONE: 419 227 3535

-----ENTITY-----

COMPANY: Orbitron Industries, Inc.
DIVISION:
P.O.BOX: 4101 Edison Lakes Parkway CITY: Mishawaka
STATE: IN
ZIP CODE: 46545 COMPANY PHONE: 219 273 0055
SPCC PLAN REQUIRED: N SPCC PLAN IN EFFECT:
REP. CONTACTED: Troy Walker TITLE: Company Rep.
PHONE 1: 219 273 0055 EXT:
PHONE 2: 419 222 3040 EXT: Frank Caprilla

----- SPILL LOCATION -----

COUNTY: Allen
CITY: Delphos
TOWNSHIP: Delphos
STREET LOCATION: 901 South Main St. (@ Orbitron Plant)

LATITUDE: 40.49.98 LONGITUDE: 84.20.36

-----PRODUCT(S) INFORMATION-----

PRODUCT / AMOUNT SPILLED / AMOUNT RECOVERED

Unknown substance Unknown Unknown

CAUSE: (3) 55 gallon drums leaking.

SOURCE: 55 gallon drums with an unknown substance.

WATERWAY: None

WATERSTAGE: Ave.

LENGTH OF WATERWAY: N/A

LAND AREA: 20ft. by 50ft. gravel area.

PRE-RESPONSE ACTION: Fire Dept. installed a sand dike around material.

----- REFERRAL(S) -----

NAME: / AGENCY: / DATE:
Maryann Alford OEPA/DHWM 06/02/94

----- EXPENSES -----

SUPPLIES: None

PHOTOS: None

FIELD TESTS: None

LAB SAMPLES: None

----- COMMENTS -----


06/02/94 1040 hours- I met Chief Seavers (Delphos Fire Dept.; 419 222 5767) at the Orbitron Plant. The Plant has been vacant for approximately 8 months, and was being sold by Orbitron Industries (Tom Cooper, Pres.; 219 273 0055) through Yocum Realty (Frank Caprilla; 419 222 3040). The three 55 gallon drums which had lost their contents were located on the south side of the plant's main building adjacent to approximately 10 other 55 gallon drums under a metal roof storage area. The black substance which had leaked out from the drums had migrated down gradient across a gravel/soil drive area, and appeared to have soaked into the ground. The Delphos Fire Dept. installed a

OHIO EPA, EMERGENCY RESPONSE GROUP
DISTRICT OFFICE INVESTIGATION REPORT


earth dike around the spilled material to prevent further migration. I contacted Mr. Troy Walker (Orbitron Company Rep.) who stated that the waste materials from the old plant were going to be disposed of soon, and that Cousins Waste Control had sampled some of the drums located inside the plant, but he was not sure if the drums on the south side of the plants exterior had been sampled. I provided Mr. Walker with two local clean-up contractors, and he hired Interdyne (Chris Cotterill; Safety Rep.; 419 229 8192) to clean-up the spilled material from the three drums. While at the site, Chief Seavers showed Mr. Ed D'Amato (OEPA/SI) and myself around the plant site. Several drums were observed on the property (some which had leaked inside the plant), in addition to areas which contained asbestos, and other containers labeled with flammable, oxidizing, and corrosive labels. There were four empty drums on the property which were marked radioactive. I checked these drums with the OEMA Rad meter and did not detect any radioactive in the area. In a small storage building on the west side of the main plant four drums of a black petroleum substance were located in addition to small containers labeled flammable. Before leaving the site, I met Mr. Cotterill, who stated that he would have crews out today to clean-up the spilled material. This incident has been referred to OEPA/DHWM for further action.

ORBITRON
DELPHOS, ALLEN COUNTY
JUNE 3, 1994

1. Drum storage area





2. Drum labeled "Used
Solvent" in Oil House




ORBITRON
DELPHOS, ALLEN COUNTY
JUNE 3, 1994

3. Drums on loading dock at rear
of main building



ORBITRON
DELPHOS, ALLEN COUNTY
JUNE 3, 1994

4. Drums/containers in main building



6/3/94 ORBITRON (ALLEN CO.)

1300 hours

Jim OTTARSON, DEPA

Wayne Suerer, Delphos Fire Dept

Troy Walker, Orbitron

Frank Caprilla, Youn Realty

did site walkover; took 7 pictures; got
quasi-analytical on some barrels in main bldg.


→ Cousins

- get
saw
me
- * - analytical on drums
 - * - spill areas (3)
 - (?) * - boxes of oxidizer

Corbin asbestos -
acid - 1 container

outdoor pole barrel vents ✓
oil house oil ✓
in main bldg batteries ✓

main bldg, near doors
white powder

(4?)
3 drums (radio)

8-9 drums

4 petroleum(?) drums

10-12
drums/spill

is same(?) may be

- Corbin
- * look area indoors, containers marked: flammable
oxidizing
corrosive
 - ✓ asbestos

TROY WALKER

4101 EDISON LAKES PKWY

MISHAWAKA, IN 46545

219-273-0055

Wed NOV \Rightarrow 52-11 for drums outside & inside
get (outside); send (already done
for inside) - analytical

cc: Suever * info on past disposal (MEK,
solvents)

* quantities of waste?

* need to remove 3 open drums

many drums, ~~mixed~~ many in poor condition
about $\frac{1}{2}$ are full; most unlabelled &
contents unknown

main areas:

1) outdoor storage area ~ 70 drums
2 labelled used MEK - no security in
3 open this area

stained soil

2) inside main bldg ~ 40 drums
many were polymeric resin
others unlabelled

3) loading dock ~ 40 drums no security

4) oil house ~ 8 drums no security

1 labelled used solvent
several used oil

property to be sold to Chester Cary of Lima

* TSD?/SIU?

* closure?

* discuss w/ MA, CW

CC NOV to Chief Sweeney

Page 1

Generator: Orbitron
901 South Main Street
Delphos, OHIO
Troy Walker
1-800-829-4536
1-219-273-0055

FILENAME: ORBITRON.01

TASK #: ORB : 01

Sampling
03/24/94

Time: 7 hours

Supplies:

Tyvek	Bung Wrenches
Gloves	Hammer
Safety Glasses	Screwdriver
Respirator	Drum Deheader
9 jars (qt)	Sampling Ladle
Paint Marker	Sampling Scoop (large)
3 sampling tubes	Crowbar
pH Paper	15/16 inch ratchet
Water Paper	

There are a total of 43 empties, 33 of which are on the dock behind the building and the other 10 are located along the fence in the rear of the facility.

The numbered drums are #1 thru #13. All were sampled except #2 and #3. These are among the empty containers.

DRUMS	AMT.	TYPE	CONDITION
1	1/2 full	55-gal., steel, CT	need small bung
4	3/4 full	55-gal., steel, OT	Good
5	1/2 full	55-gal., steel, OT	Good
6	FULL	55-gal., steel, CT	need both bungs

Page 1-A (continued)

Generator: Orbitron
901 South Main Street
Delphos, OHIO
Troy Walker
1-800-829-4535
1-219-273-0055

FILENAME: ORBITRON.01

TASK #: ORB : 01

Sampling
03/24/94

DRUMS	AMT.	TYPE	CONDITION
7	7 inches	55-gal.,steel,OT	Good
8	FULL	55-gal.,steel,CT	need small bung,bottom is bulging
9	6 inches	55-gal.,steel,OT	Good.
10	6 inches	55-gal.,steel,OT	need lid
11	12 inches	55-gal.,steel,OT	need lid
12	FULL	55-gal.,steel,OT	Good
13	FULL	55-gal.,steel,OT	Good

Drums #1,4,5,6,7,8,& #9:

Located along the fence area.

Drums #10,11,12, & #13:

Located on the dock area among the empties.

TASK #: ORB : 01 FILENAME: ORBITRON.01
 GENERATOR: Orbitron
 SAMPLES STORAGE: brown box: Orbitron 3-24-94

SALESPERSON: sft
 SAMPLED BY: bl
 DATE SAMPLED: 03/24/1994
 DATE SCREENED: 03/25/1994
 SCREENED BY: bl

LAB NUMBER	4461	4462	4463	4464	4465
WASTE NAME					
pH	5-7	5-7	5-7	5-7	5-7
FLASH POINT (deg F)	>200	none	none	none	>200
X-MET 820 (Cl%)	negative	negative	negative	negative	87% Solid HIGH
SP.GRAVITY(H2O=1.0)	0.986	0.99	0.978	0.976	1.11
LQ%-SLUDGE%-SOLID%	100%LQ	100%LQ	100%LQ	100%LQ	100%LQ
WATER %	>50%	>50%	>50%	>50%	0%
WATER SOLUBILITY	complete	complete	complete	complete	no
ODOR	mild	low	none	low	vinyl
COLOR/APPEARANCE	Brown Slightly Translucent Low Viscosity	Light Brown Slightly Transparent Low Viscosity	lt. gray to cloudy slightly transparent Low Viscosity	lt.brn. to cloudy transparent Low Viscosity	Black completely opaque highly viscous & cohesive
PHASES	one	one	one	one	one
DRUM NUMBERS	1	4	5	6	7

TASK #: ORB : 01 FILENAME: ORBITRON.01
GENERATOR: Orbitron
SAMPLES STORAGE: brown box: Orbitron 3-24-94

SALESPERSON: sft
SAMPLED BY: bl
DATE SAMPLED: 03/24/1994
DATE SCREENED: 03/25/1994
SCREENED BY: bl

LAB NUMBER	4466	4467	4468	4469	
WASTE NAME	DRUM 8	DRUM 9	DRUM 10 & 11	DRUM 12 & 13	
PH	5-7	5-7	5-7	5-7	
FLASH POINT (deg F)	none	>200	>200	>200	
X-MET 820 (CI%)	negative	BFA 8,000 HIGH	BFA 8,000 HIGH	BFA 8,000 HIGH	
SP.GRAVITY(H2O=1.0)	0.996	1.13	1.12	1.07	
LQ%-SLUDGE%-SOLID%	100%LQ	100%LQ	100%LQ	100%LQ	
WATER %	>50%	0%	0%	0%	
WATER SOLUBILITY	complete	no	no	no	
ODOR	none	vinyl	vinyl	vinyl	
COLOR/APPEARANCE	Crystal clear completely transparent low viscosity	Black completely opaque highly viscous & cohesive	Yellow completely opaque highly viscous & cohesive	Black completely opaque highly viscous & cohesive	
PHASES	one	one	one	one	
DRUM NUMBERS	8	9	10 & 11 (composited)	12 & 13 (composited)	
COMMENTS:					

FAX 2192730918

ORBITRON

P01

ORBITRON INDUSTRIES, INC.
4101 EDISON LAKES PARKWAY
SUITE 160
MISHAWAKA, IN 46565
(219) 273-0055
(219) 273-0918 FAX

TO: JOHN MONGELLUZZO

COMPANY: YOCUM REALTY

FAX #: 419 227-6108

FROM: TROY WALKER

COMPANY: ORBITRON

DATE: 4-22-94

NUMBER OF PAGES TO FOLLOW: 3

COMMENTS: JOHN, THE TOTAL PRICE FOR THE

ASBESTOS REMOVAL AND DRUM REMOVAL IS

\$17,635.00

Troy

IF YOU DO NOT RECEIVE ALL PAGES OR ANY ARE UNCLEAR, PLEASE CALL OUR
OFFICE NUMBER (219) 273-0055

ALLIED

April 21, 1994

TO: Mr. Troy Walker, Orbitron...
RE: Delphon Abatement Survey

Please review the following asbestos abatement survey figures. These may be of assistance to you in planning the real estate transfer.

A. Finishing Area -- Glovebag 275 linear feet of asbestos laggings. Estimated Cost Not-To-Exceed: \$5,500.00.

B. Kiln Area. Glovebag 190 linear feet of asbestos laggings. Estimated Cost Not-To-Exceed: \$3,800.00

C. Enclose Boiler Room. \$5,500.00

Submitted by,

Steve Hamblen
President

SPH/sp/ORBITRON

\$14,800.00



Waste Control • Environmental Services • Dust Control
PROVIDING QUALITY SERVICES SINCE 1971

1801 Matzinger Road
Tipton, Ohio 43082
(419) 729-1500 • (800) 433-8754

SALES FAX:
(419) 729-8501

April 12, 1994

MAIN FAX:
(419) 729-8507

ENVIRONMENTAL FAX:
(419) 729-8508

Mr. Troy Walker
Orbitron Corp.
4101 Edison Lake Parkway
Mishawaka, IN 46545

Re: ORB01

Dear Troy:

The following is a quotation for the drums of vinyl coating and water soluble paint that our Technical Services Field Technician sampled on March 24, 1994.

We are able to combine these materials into two (2) waste streams and the cost will be as follows:

Drum #1,4,5,6, and 8

Water Soluble Paint

Chem-Met Approval Fee

Disposal Cost

\$ 150.00 flat

\$ 130.00 per drum

Drum #7,9,10,11,12, and 13

Vinyl Coating

Petro-Chem Processing Fee

Disposal Cost

\$ 150.00 flat

\$ 115.00 per drum

Please note, before we can proceed, Cousins Waste Control would require the two (2) approval fees up front for a total of \$300.00.

Once approved, based on the number of drums you now have for disposal, your cost will be as follows:

Five drums for disposal at Chem-Met

\$ 650.00

Six drums for disposal at Petro-Chem

\$ 690.00

Transportation for pick-up and
disposal on a "milk-run" only

\$ 350.00

Your total cost will be

\$1,690.00

NOTE: This excludes the \$300.00 for approval fees -----



COUSINS

Waste Control • Environmental Services • Dust Control
PROVIDING QUALITY SERVICES SINCE 1971...

1801 Matzinger Road
Toledo, Ohio 43612
(419) 729-1800 • (800) 488-8754

SALES FAX:
(419) 729-8501

MAIN FAX:
(419) 729-8507

ENVIRONMENTAL FAX:
(419) 729-8508

March 30, 1994

Mr. Troy Walker
Orbltron
901 S. Main St.
Delphos, OH 45833

Re: ORB01

Dear Troy:

The following is your quotation is for transportation and disposal of 43 empty drums:

Disposal @ \$15.00 each	\$645.00
Transportation - flat fee	\$200.00

Total due at time of pick-up \$845.00

Make check payable to Cousins Waste Control and send it back with the driver.

Our dispatcher will call you with a date and time of the pick-up so you can meet our driver. I will get in touch with you on the other waste materials as soon as I get the results.

Acceptance of this quotation or completion of services stated above indicates that you agree to stated prices, terms of payment, and all standard Terms and Conditions listed on the reverse side.

If prices are acceptable, please sign the acknowledgment below and return to me in the envelope provided.

If you have any questions, please contact me. Thank you for the opportunity to provide service.

Sincerely,

Shirley Fitch-Thorzynski

Shirley Fitch-Thorzynski
Technical Sales Representative
Cousins Waste Control Corporation

SFT/wr/erb01.1

Accepted By _____ Date _____

Purchase Order Number (if applicable) _____



Recycled Paper

COMPLAINT INVESTIGATION FORMDATE/TIME REPORTED: 6/2/94DISTRICT OFFICE NWDO #1060**COMPLAINANT:**Name: Tom TilsonAddress: Allen Co Emergency ManagementPhone No.: (419) 227-3535*Confidential Status: Y/N

Comments: _____

SUSPECTED SOURCE:Name/Facility: Orbitron IndustriesAddress: 901 S Main StDelphosCounty: ALLEN SUBD 2

Phone No.: _____

Regulatory Status: SQG G T TSD Unreg Cond Ex

USEPA/OHIO ID# _____

STATEMENT OF COMPLAINT: *(Location, type of material, quantity, areas affected, phone #'s)*Three 55-gal drums leaking. Approximately 125 drums on-site (indoors & outdoors).

Contents unknown. DERR on-scene coordinator met w/fire chief @ site 6/2/94. South side
of plant's main bldg found the 3 leaking drums. Black substance from drums had migrated
down across gravel/soil driveway & had soaked into ground. Earthen dike installed around
spilled material. Facility rep contacted. Interdyne contracted for cleanup. Many HW labeled
drums on-site. Some areas contained asbestos. See ER Report.

ASSOCIATED INDIV./COMPANIES: _____

COMPLAINT RECEIVED BY: M Gerber/DERR/NWDO**INVESTIGATION SUMMARY:** *(Use separate summary sheet if handled by district)*

INVESTIGATOR ASSIGNED: _____ PRIORITY: _____

ACTIONS/OBSERVATIONS/RECOMMENDATIONS: _____

INVESTIGATION STATUS/RESOLUTION: _____

1060

OHIO EPA, EMERGENCY RESPONSE GROUP
DISTRICT OFFICE INVESTIGATION REPORTSPILL #: 9406-02-2414 STATUS: F01
DATE SUBMITTED: 06/03/94 ON SCENE COORDINATOR: J.M.Gerber

REPORTED: 0905 06/02/94 DISCOVERED: 0800 06/02/94 OCCURRED: 10/93

REPORTED BY: Tom Tilson PHONE: 419 227 3535

-----ENTITY-----

COMPANY: Orbitron Industries, Inc.
DIVISION:
P.O.BOX: 4101 Edison Lakes Parkway CITY: Mishawaka
STATE: IN
ZIP CODE: 46545 COMPANY PHONE: 219 273 0055
SPCC PLAN REQUIRED: N SPCC PLAN IN EFFECT:
REP. CONTACTED: Troy Walker TITLE: Company Rep.
PHONE 1: 219 273 0055 EXT:
E 2: 419 222 3040 EXT: Frank Caprilla

----- SPILL LOCATION -----

COUNTY: Allen
CITY: Delphos
TOWNSHIP: Delphos
STREET LOCATION: 901 South Main St. (@ Orbitron Plant)

LATITUDE: 40.49.98 LONGITUDE: 84.20.36

-----PRODUCT(S) INFORMATION-----

PRODUCT / AMOUNT SPILLED / AMOUNT RECOVERED

Unknown substance Unknown Unknown

CAUSE: (3) 55 gallon drums leaking.

SOURCE: 55 gallon drums with an unknown substance.

WATERWAY: None

WATERSTAGE: Ave. LENGTH OF WATERWAY: N/A

LAND AREA: 20ft. by 50ft. gravel area.

RESPONSE ACTION: Fire Dept. installed a sand dike around material.

----- REFERRAL(S) -----

NAME: / AGENCY: / DATE:
Maryann Alford OEPA/DHWM 06/02/94

----- EXPENSES -----

SUPPLIES: None
PHOTOS: None
FIELD TESTS: None
LAB SAMPLES: None

----- COMMENTS -----

06/02/94 1040 hours- I met Chief Seavers (Delphos Fire Dept.; 419 222 5767) at the Orbitron Plant. The Plant has been vacant for approximately 8 months, and was being sold by Orbitron Industries (Tom Cooper, Pres.; 219 273 0055) through Yocum Realty (Frank Caprilla; 419 222 3040). The three 55 gallon drums which had lost their contents were located on the south side of the plant's main building adjacent to approximately 10 other 55 gallon drums under a metal roof storage area. The black substance which had leaked out from the drums had migrated down gradient across a gravel/soil drive area, and appeared to have soaked into the ground. The Delphos Fire Dept. installed a

OHIO EPA, EMERGENCY RESPONSE GROUP
DISTRICT OFFICE INVESTIGATION REPORT

earth dike around the spilled material to prevent further migration. I contacted Mr. Troy Walker (Orbitron Company Rep.) who stated that the waste materials from the old plant were going to be disposed of soon, and that Cousins Waste Control had sampled some of the drums located inside the plant, but he was not sure if the drums on the south side of the plants exterior had been sampled. I provided Mr. Walker with two local clean-up contractors, and he hired Interdyne (Chris Cotterill; Safety Rep.; 419 229 8192) to clean-up the spilled material from the three drums. While at the site, Chief Seavers showed Mr. Ed D'Amato (OEPA/SI) and myself around the plant site. Several drums were observed on the property (some which had leaked inside the plant), in addition to areas which contained asbestos, and other containers labeled with flammable, oxidizing, and corrosive labels. There were four empty drums on the property which were marked radioactive. I checked these drums with the OEMA Rad meter and did not detect any radioactive in the area. In a small storage building on the west side of the main plant four drums of a black petroleum substance were located in addition to small containers labeled flammable. Before leaving the site, I met Mr. Cotterill, who stated that he would have crews out today to clean-up the spilled material. This incident has been referred to OEPA/DHWM for further action.

FOR
CLEVELAND
TAT OFFICE

Post-It™ Fax Note	7671	Date	7/7/94	# of pages	3
To	GAIL NABASNY		From	S. RENNINGER	
Co./Dept.	HSE-SS		Co.	F.P. SITE	
Phone #	353-1086		Phone #	419-547-7683	
Fax #	353-9176		Fax #		

TDD# _____ PCS# _____ DUE DATE 9/30/94

SITE NAME ORBITRON SITE ID# _____

LOCATION DELPHOS ALLEN OHIO
City County State

PRIORITY (H M L) _____ FUNDS (311 CERCLA) _____

REFERENCE MATERIAL OHIO EPA FILES O.T. Yes / No

REPORT FORMAT SITE INVESTIGATION HOURS 120 \$ _____

ASSIGNOR _____ ACCEPTED BY _____

OSC RENNINGER DATE _____ TIME _____

GENERAL TASK DESCRIPTION (Check ONE of the following):

TDD TYPE CODES

CERCLA ONLY

- 01 ☒ Site Investigations (CERCLA 104b) *
- 11 [] Removals (Funded) (CERCLA 104c) *
- 21 [] Removals (PRP) *
- 31 [] On-Scene Monitoring *
- 41 [] Release Investigation *
- 51 [] EECAs *
- 61 []

311 ONLY

- 02 [] SFOCs
- 12 [] Monitoring Oversight (PRP)
- 22 [] Clean-up (Funded)
- 32 []

UST ONLY

- 03 [] UST Support

Other**

- 05 [] Training (Received)
- 15 [] Training (Given)
- 06 [] Special Projects
- 16 [] Analytical Services
- 26 [] TAT Support-Analytical Services
- 36 [] RCRA Site Investigations
- 46 [] Contingency Planning
- 56 [] General Technical Assistance
- 66 [] Title III (CEPP Support, etc.)
- 07 [] Program Management
- 17 [] Cost Recoveries
- 27 [] Quality Assurance Support
- 37 [] Equipment Maintenance (TAT Equipment Only)
- 47 [] Information Management

FEMA

- 04 [] FEMA Support

* Must have a site code.

** May have a site code.

TOD TASKING ASSIGNMENTSpecific Elements (Check and/or fill ALL Elements that apply to your task):**ADMINISTRATIVE**

<u>TASK</u>	<u>INTERIM DUE DATE</u>	<u>TASK</u>	<u>INTERIM DUE DATE</u>
<input type="checkbox"/> Organize/Review Files	_____	<input type="checkbox"/> Research Information on	_____
<input type="checkbox"/> Prepare Computer Program as	_____	Subject Requested by OSC	_____
Further Defined by the OSC*	_____	<input type="checkbox"/> Present Training	_____
<input type="checkbox"/> Logistics Support	_____	<input type="checkbox"/> Attend Training	_____
<input type="checkbox"/> Graphics/Charts	_____	<input type="checkbox"/> Conduct Inventory	_____
<input type="checkbox"/> Other	_____	<input type="checkbox"/> Other _____	_____

* Must coordinate with ZEMO to preclude duplicative effort.

SITE INVESTIGATIONS

<input checked="" type="checkbox"/> Prepare & Implement Health & Safety Plan	7/12/94	<input checked="" type="checkbox"/> Document On-Site Activities	7/12/94
<input checked="" type="checkbox"/> Compile Available Info.	_____	<input type="checkbox"/> Conduct Windshield Survey	_____
<input checked="" type="checkbox"/> Perform Site Inspection	_____	<input checked="" type="checkbox"/> Provide Photo Documentation	_____
<input checked="" type="checkbox"/> Conduct Air Monitoring	_____	<input type="checkbox"/> Provide Engineering Assistance	_____
<input checked="" type="checkbox"/> Evaluate Threat to Human Health & Environment	_____	<input type="checkbox"/> Prepare/Assist with Action Memo	_____
<input type="checkbox"/> Develop Alternative Removal Approaches with Cost Est.	_____	<input checked="" type="checkbox"/> Other <u>VIDEOTAPE</u>	_____
<input checked="" type="checkbox"/> Verbal Briefing to DFO <u>OSC</u>	_____	<input checked="" type="checkbox"/> Other <u>ASSIST w/ ACP SEARCH</u> (FILES)	_____
<input checked="" type="checkbox"/> Prepare & Implement Sampling Plan	_____		
<input checked="" type="checkbox"/> Conduct Extent of Contamination Study	_____		

REMOVALS - OSC SUPPORT

(CERCLA Funded)	(ERP Funded)
<input type="checkbox"/> Maintain CERCLA Paperwork	<input type="checkbox"/> Document ERP Cleanup Activities
<input type="checkbox"/> Monitor Contractor Perform.	<input type="checkbox"/> Provide Photo Documentation
<input type="checkbox"/> Site Safety Officer	<input type="checkbox"/> Video Documentation
<input type="checkbox"/> Prepare Removal Action Safety Plan	<input type="checkbox"/> Conduct QC Sampling
<input type="checkbox"/> Conduct Air Monitoring	<input type="checkbox"/> Review ERP Safety Plan
<input type="checkbox"/> Prepare Sampling Plan	<input type="checkbox"/> Oversight of Site Safety
<input type="checkbox"/> Conduct Multimedia Sampling	<input type="checkbox"/> Prepare Outline for After-Action Report
<input type="checkbox"/> Prepare Polyneps	<input type="checkbox"/> Other _____
<input type="checkbox"/> Prepare Contingency Plan	<input type="checkbox"/> Other _____
<input type="checkbox"/> Provide Photo Documentation	
<input type="checkbox"/> Video Tape Action	
<input type="checkbox"/> Organize Site Files Accord. to OSC Appendices	
<input type="checkbox"/> Prepare Outline of After-Action Report	
<input type="checkbox"/> Containment of Release	

EMERGENCY RESPONSE

<u>TASK</u>	<u>INTERIM DUE DATE</u>	<u>TASK</u>	<u>INTERIM DUE DATE</u>
[] Conduct Air Monitoring	_____	[] Maps and Sketches	_____
[] Conduct Multimedia Sampling	_____	[] Data Base Technical Services	_____
[] Photo Documentation	_____	[] Video Documentation	_____
[] Prepare Palrep	_____	[] FRP Search	_____
[] Chronology of Events	_____	[] Other _____	_____
[] Other _____	_____		

PLANNING AND INSPECTIONS

[] Conduct SPOC Inspection	_____	[] Review SPOC Plan	_____
[] Conduct TSCA Inspection	_____	[] Assist with Regional Contingency Plan	_____
[] Conduct RCRA Inspection	_____	[] Review State Contingency Plan	_____
[] Conduct ILST Inspection	_____	[] Assist CEPP Preparation/Presentation	_____
[] Prepare Inspection Reports	_____	[] Other _____	_____
[] Other _____	_____		

COMMUNITY RELATIONS

[] Design Graphics	_____	[] Develop Contact List	_____
[] Interview Public Officials	_____	[] Interview Residents	_____
[] Prepare Exhibit/ Audio-Visual Aid	_____	[] Prepare Presentation	_____
[] Arrange Site Tour	_____	[] Provide Support for Public Meeting	_____
[] Conduct Community Survey	_____	[] Prepare Chronology	_____
[] Design & Conduct Workshops	_____	[] Arrange Briefings/News Conference	_____
[] Other _____	_____	[] Other _____	_____
[] Other _____	_____		

MISCELLANEOUS INFORMATION

1. REVIEW OHIO EPA FILES / SITE BACKGROUND
2. REVIEW EPA SITE VIDEO W/ OSC BY 7/12/94.
3. COORDINATE SITE INVESTIGATION W/ OSC.

Ohio EPA

Case No. _____

COMPLAINT INVESTIGATION FORMDATE/TIME REPORTED: 6/2/94DISTRICT OFFICE NWDO #1060**COMPLAINANT:**Name: Tom TilsonAddress: Allen Co Emergency ManagementPhone No.: (419) 227-3535Confidential Status: Y/N

Comments: _____

SUSPECTED SOURCE:Name/Facility: Orbitron IndustriesAddress: 901 S Main StDelphosCounty: ALLENSUBD 2

Phone No.: _____

Regulatory Status: SOQ G T TSD Unreg Cond Ex

USEPA/OHIO ID# _____

STATEMENT OF COMPLAINT: (Location, type of material, quantity, areas affected, phone #'s)Three 55-gal drums leaking. Approximately 125 drums on-site (indoors & outdoors).

Contents unknown. DERR on-scene coordinator met w/fire chief @ site 6/2/94. South side of plant's main bldg found the 3 leaking drums. Black substance from drums had migrated down across gravel/soil driveway & had soaked into ground. Earthen dike installed around spilled material. Facility rep contacted. Interdyne contracted for cleanup. Many HW labeled drums on-site. Some areas contained asbestos. See ER Report.

ASSOCIATED INDIV./COMPANIES: _____

COMPLAINT RECEIVED BY: M Gerber/DERR/NWDO**INVESTIGATION SUMMARY:** (Use separate summary sheet if handled by district)

INVESTIGATOR ASSIGNED: _____

PRIORITY: _____

ACTIONS/OBSERVATIONS/RECOMMENDATIONS: _____

INVESTIGATION STATUS/RESOLUTION: _____

Post-It Fax Note

7671

Date	<u>7/8/94</u>	# of pages	<u>3</u>
To	<u>DEBORAH DAWLEY</u>		
Co./Dept.	<u>S. RENNINGER</u>		
Phone #	<u>312-353-9176</u>		
Fax #	<u></u>		

1060

OHIO EPA, EMERGENCY RESPONSE GROUP
DISTRICT OFFICE INVESTIGATION REPORTSPILL #: 9406-02-2414 STATUS: F01
DATE SUBMITTED: 06/03/94 ON SCENE COORDINATOR: J.M.Gerber

REPORTED: 0905 06/02/94 DISCOVERED: 0800 06/02/94 OCCURRED: 10/93

REPORTED BY: Tom Tilson

PHONE: 419 227 3535

-----ENTITY-----

COMPANY: Orbitron Industries, Inc.

DIVISION:

P.O.BOX: 4101 Edison Lakes Parkway CITY:

Mishawaka

STATE: IN

ZIP CODE: 46545

COMPANY PHONE: 219 273 0055

SPCC PLAN REQUIRED: N

SPCC PLAN IN EFFECT:

PERSON CONTACTED: Troy Walker TITLE: Company Rep.

PHONE 1: 219 273 0055

EXT:

PHONE 2: 419 222 3040

EXT: Frank Caprilla

----- SPILL LOCATION -----

COUNTY: Allen

CITY: Delphos

TOWNSHIP: Delphos

STREET LOCATION: 901 South Main St. (Ø Orbitron Plant)

LATITUDE: 40.49.98

LONGITUDE: 84.20.36

-----PRODUCT(S) INFORMATION-----

PRODUCT / AMOUNT SPILLED / AMOUNT RECOVERED

Unknown substance Unknown Unknown

CAUSE: (3) 55 gallon drums leaking.

SOURCE: 55 gallon drums with an unknown substance.

WATERWAY: None

WATERSTAGE: Ave.

LENGTH OF WATERWAY: N/A

LAND AREA: 20ft. by 50ft. gravel area.

POST RESPONSE ACTION: Fire Dept. installed a sand dike around material.

----- REFERRAL(S) -----

NAME: /

AGENCY: /

DATE:

Maryann Alford

OEPA/DHWM

06/02/94

----- EXPENSES -----

SUPPLIES: None

PHOTOS: None

FIELD TESTS: None

LAB SAMPLES: None

----- COMMENTS -----

06/02/94 1040 hours- I met Chief Seavers (Delphos Fire Dept.; 419 222 5767) at the Orbitron Plant. The Plant has been vacant for approximately 8 months, and was being sold by Orbitron Industries (Tom Cooper, Pres.; 219 273 0055) through Yocum Realty (Frank Caprilla; 419 222 3040). The three 55 gallon drums which had lost their contents were located on the south side of the plant's main building adjacent to approximately 10 other 55 gallon drums under a metal roof storage area. The black substance which had leaked out from the drums had migrated down gradient across a gravel/soil drive area, and appeared to have soaked into the ground. The Delphos Fire Dept. installed a

**OHIO EPA, EMERGENCY RESPONSE GROUP
DISTRICT OFFICE INVESTIGATION REPORT**

earth dike around the spilled material to prevent further migration. I contacted Mr. Troy Walker (Orbitron Company Rep.) who stated that the waste materials from the old plant were going to be disposed of soon, and that Cousins Waste Control had sampled some of the drums located inside the plant, but he was not sure if the drums on the south side of the plants exterior had been sampled. I provided Mr. Walker with two local clean-up contractors, and he hired Interdyne (Chris Cotterill; Safety Rep.; 419 229 8192) to clean-up the spilled material from the three drums. While at the site, Chief Seavers showed Mr. Ed D'Amato (OEPA/SI) and myself around the plant site. Several drums were observed on the property (some which had leaked inside the plant), in addition to areas which contained asbestos, and other containers labeled with flammable, oxidizing, and corrosive labels. There were four empty drums on the property which were marked radioactive. I checked these drums with the OEPA Rad meter and did not detect any radioactive in the area. In a small storage building on the west side of the main plant four drums of a black petroleum substance were located in addition to small containers labeled flammable. Before leaving the site, I met Mr. Cotterill, who stated that he would have crews out today to clean-up the spilled material. This incident has been referred to OEPA/DHWM for further action.

PRINT DOC REQUESTED: JULY 11, 1994
3 DOCUMENTS PRINTED
4 PRINTED PAGES

1002MP

SEND TO: CHABRIA, MONESH
ENVIRONMENTAL PROTECTION AGENCY-CHICAGO
OFFICE OF REGIONAL COUNSEL
77 W JACKSON BLVD MAIL CODE C-3T

CHICAGO ILLINOIS 60604

*****02393*****

PAGE 1

DATE: JULY 11, 1994

CLIENT: CERCLA, ORBITRON
LIBRARY: INCORP
FILE: INSOS

YOUR SEARCH REQUEST IS:
ORBITRON OR MTI

NUMBER OF DOCUMENTS FOUND WITH YOUR REQUEST THROUGH:
LEVEL 1... 10

PAGE 2

1ST DOCUMENT of Level 1 printed in FULL format.

*** THIS DATA IS FOR INFORMATION PURPOSES ONLY. CERTIFICATION CAN ONLY BE OBTAINED THROUGH THE OFFICE OF THE INDIANA SECRETARY OF STATE. ***

INDIANA SECRETARY OF STATE, CORPORATE/LTD PARTNERSHIP RECORDS

NAME: BOBICK, INC.

TYPE: DOMESTIC CORPORATION FOR-PROFIT

STATUS: ACTIVE

DATE OF INCORPORATION/QUALIFICATION: 06/23/1986

ACTS: PROFIT

MAILING ADDRESS: CT CORPORATION SYSTEM
ONE N CAPITOL
INDIANAPOLIS, IN 46204

REGISTERED AGENT: C T CORPORATION SYSTEM

REGISTERED OFFICE: 1 N CAPITOL AVE
INDIANAPOLIS, IN 46204

ANNUAL-REPORT: 1986, 1987, 1988, 1989, 1990, 1991, 1992, 1993

PRESIDENT: Thomas Cooper
1100 W. Beardsley
Elkhart, IN 46515

SECRETARY: Scott Lefky
954 SHORELINE RD.
BARRINGTON, IL 60010

FEIN: 363459147

NUMBER: 198606-778

PRIOR-NAMES: ORBITRON INDUSTRIES INC, name changed as of 10/12/1993

HISTORY: ANNUAL REPORT DOMESTIC FOR-PROFIT
FILED: 08/02/1989, EFFECTIVE: 08/02/1989

INFORMATION REQUEST
FILED: 07/09/1993, EFFECTIVE: 07/09/1993

ANNUAL REPORT DOMESTIC FOR-PROFIT

FILED: 07/09/1993, EFFECTIVE: 07/09/1993

AMENDMENT TO ARTICLES OF INCORPORATIONS FOR-PROFIT

FILED: 10/12/1993, EFFECTIVE: 10/12/1993

ENTER LEXDOC TO ORDER COPIES OF THE ORIGINAL FILING AND RELATED DOCUMENTS

PAGE 3

3RD DOCUMENT of Level 1 printed in FULL format.

*** THIS DATA IS FOR INFORMATION PURPOSES ONLY. CERTIFICATION CAN ONLY BE OBTAINED THROUGH THE OFFICE OF THE INDIANA SECRETARY OF STATE. ***

INDIANA SECRETARY OF STATE, CORPORATE/LTD PARTNERSHIP RECORDS

NAME: MANUFACTURING TECHNOLOGY INC

ASSUMED-NAME: MTI

TYPE: DOMESTIC CORPORATION FOR-PROFIT

STATUS: MERGED OUT OF EXISTENCE AS OF 10/31/1991

STATUS-COMMENT: Merged corporate number: 198011-368

DATE OF INCORPORATION/QUALIFICATION: 01/22/1976

ACTS: PROFIT

MAILING ADDRESS: 17741 WOOD RIDGE DR
SOUTH BEND, IN 46615

REGISTERED AGENT: CONRAD R ADAMS II

REGISTERED OFFICE: 17741 WOOD RIDGE
SOUTH BEND, IN 46000

ANNUAL-REPORT: 1983, 1984, 1985, 1986, 1987, 1988, 1989, 1990, 1991

PRESIDENT: ADAMS.II. CONRAD. R.
17741 WOODRIDGE
SOUTH BEND

SECRETARY: ADAMS.MARY. R.
17741 WOODRIDGE
SOUTH BEND

FEIN: 351363983

NUMBER: 197601-456

HISTORY: ANNUAL REPORT DOMESTIC FOR-PROFIT
FILED: 05/05/1988, EFFECTIVE: 05/05/1988

RESTATEMENT OF ARTICLES OF INCORPORATION
FILED: 07/08/1988, EFFECTIVE: 07/08/1988

ENTER LEXDOC TO ORDER COPIES OF THE ORIGINAL FILING AND RELATED
DOCUMENTS

PAGE 4

10TH DOCUMENT of Level 1 printed in FULL format.

*** THIS DATA IS FOR INFORMATION PURPOSES ONLY. CERTIFICATION CAN ONLY BE OBTAINED THROUGH THE OFFICE OF THE INDIANA SECRETARY OF STATE. ***

INDIANA SECRETARY OF STATE, CORPORATE/LTD PARTNERSHIP RECORDS

NAME: NEC BUSINESS COMMUNICATION SYSTEMS (CENTRAL), INC.

TYPE: FOREIGN CORPORATION FOR-PROFIT

STATUS: REVOKED AS OF 08/05/1993

DATE OF INCORPORATION/QUALIFICATION: 11/27/1989
Original Incorporation: 11/18/1988

ACTS: PROFIT

MAILING ADDRESS: 32 Woodlake Drive East
Woodbury, NY 11797

STATE OF INCORPORATION: DELAWARE

REGISTERED AGENT: Prentice Hall

REGISTERED OFFICE: Circle Tower
Indianapolis, IN 46204

ANNUAL-REPORT: 1990

PRESIDENT: Thomas J. Burger
7134 Melrose Castle Ln.
Boca Raton, FL 33496

SECRETARY: Hidekatsu Makino
1923 19th Ln.
Lake Worth, FL 33463

NUMBER: 1989110893

PRIOR-NAMES: MTI BUSINESS COMMUNICATION SYSTEMS, INC., name
changed as of 02/28/1990

HISTORY: CERTIFICATE OF AUTHORITY
FILED: 11/27/1989, EFFECTIVE: 11/27/1989

AMENDED CERTIFICATE OF AUTHORITY
FILED: 02/28/1990, EFFECTIVE: 02/28/1990

CHANGE OF REGISTERED OFFICE

FILED: 10/16/1993, EFFECTIVE: 10/16/1993

**ENTER LEXDOC TO ORDER COPIES OF THE ORIGINAL FILING AND RELATED
DOCUMENTS**

-----*****

* 5 PAGES 103 LINES
*
* 2:09 P.M. STARTED 2:10 P.M. ENDED
*

-----*****

-----*****

*		EEEEEE	N	N	DDDD
	*				
*		E	N	N	D D
	*				
*		E	NN	N	D D
	*				
*		EEE	N N N		D D
	*				
*		E	N NN		D D
	*				
*		E	N N		D D
	*				
*		EEEEEE	N	N	DDDD
	*				

-----*****

-----*****

**SEND TO: CHABRIA, MONESH
ENVIRONMENTAL PROTECTION AGENCY-CHICAGO
OFFICE OF REGIONAL COUNSEL
77 W JACKSON BLVD MAIL CODE C-3T
CHICAGO, ILLINOIS 60604**

MAIL-IT REQUESTED: JULY 11, 1994

1002MP

CLIENT: CERCLA, ORBITRON
LIBRARY: INCORP
FILE: OHINC

YOUR SEARCH REQUEST AT THE TIME THIS MAIL-IT WAS REQUESTED:
NAME(ORBITRON)

NUMBER OF DOCUMENTS FOUND WITH YOUR REQUEST THROUGH:
LEVEL 1... 3

LEVEL 1 PRINTED

DISPLAY FORMAT: FULL

SEND TO: CHABRIA, MONESH
ENVIRONMENTAL PROTECTION AGENCY-CHICAGO
OFFICE OF REGIONAL COUNSEL
77 W JACKSON BLVD MAIL CODE C-3T

CHICAGO ILLINOIS 60604

*****00345*****

PAGE 1

LEVEL 1 - 1 OF 3 DOCUMENTS

*** THIS DATA IS FOR INFORMATION PURPOSES ONLY. CERTIFICATION CAN ONLY BE OBTAINED THROUGH THE OFFICE OF THE OHIO SECRETARY OF STATE. ***

OHIO SECRETARY OF STATE, CORPORATE RECORD

NAME: ORBITRON PRODUCTS, INC.

TYPE: FOREIGN FOR PROFIT LICENSE

STATUS: NOT IN GOOD STANDING

DATE OF INCORPORATION/QUALIFICATION: 10/13/1969

MAILING ADDRESS: 524 W. GUTHRIE ST., UPPER SANDUSKY, OH 43351

STATE OF INCORPORATION: NEW YORK

REGISTERED AGENT: STEVEN MOORE

REGISTERED OFFICE: 901 S MAIN ST
DELPHOS
45833

CHARTER NUMBER: 389644

CAPITAL/STOCK: 268715 (shares allocated to Ohio)

HISTORY:

DATE FRAME	TRANSACTION	ROLL
----	-----	----
11/30/1990	CANCELLED BY TAXATION DEPARTMENT	
05/18/1990	FOREIGN/REINSTATEMENT	G865
1749		
	FOREIGN/AGENT SUBSEQUENT APPOINTMENT	
	'88 FORM 7, NO FEE ASSESSED	
	'89 FORM 7, NO FEE ASSESSED	
	'90 FORM 7, NO FEE ASSESSED	
	CANCELLED FOREIGN CORPORATION FOR	
	FAILURE TO FILE AND/OR PAY FEE(S) ON	
	FORM 7	G822
03/02/1990		
1843		
05/11/1987	FOREIGN/AGENT CHANGE OF ADDRESS	G154
1723		
03/31/1987	'87 FORM 7, NO FEE ASSESSED	F909
0115		
03/31/1986	'86 FORM 7, NO FEE ASSESSED	F909
0114		

0113	03/31/1985	'85 FORM 7, NO FEE ASSESSED	F909
1328	03/31/1984	'84 FORM 7, NO FEE ASSESSED	F455
1510	06/13/1983	FOREIGN/AGENT CHANGE OF ADDRESS	F267
1745	07/26/1982	'83 FORM 7, NO FEE ASSESSED	
2279	02/24/1982	'82 FORM 7, FEE ASSESSED	F108
		'81 FORM 7, FEE ASSESSED	F037
1949	01/16/1981	MERGER OF DOMESTIC INTO A FOREIGN CORPORATION	E858
		(OH 43032) INTO (NY 389644) EFF 1-20-81	
1666	00001980	'80 FORM 7, NO FEE ASSESSED	
1333	00001979	'79 FORM 7, NO FEE ASSESSED	E650
2108	00001978	'78 FORM 7, NO FEE ASSESSED	E483
	00001977	'77 FORM 7, NO FEE ASSESSED	E355

PAGE 2

	OHIO SECRETARY OF STATE, CORPORATE RECORD	
00001976	'76 FORM 7, NO FEE ASSESSED	E355
2107		
00001975	'73 FORM 7, NO FEE ASSESSED	
	ALL THRU 1975	
08/14/1972	'72 FORM 7, FEE ASSESSED	
03/20/1972	FOREIGN/AGENT SUBSEQUENT APPOINTMENT	B795
1951		
05/18/1971	'70 FORM 7, FEE ASSESSED	
	'71 FORM 7, FEE ASSESSED	
10/13/1969	FOREIGN LICENSE/FOR PROFIT	B641
0400		

* ENTER LEXDOC TO ORDER A CERTIFICATE OF GOOD STANDING OR OTHER DOCUMENTS *

PAGE 3

LEVEL 1 - 2 OF 3 DOCUMENTS

*** THIS DATA IS FOR INFORMATION PURPOSES ONLY. CERTIFICATION CAN ONLY BE OBTAINED THROUGH THE OFFICE OF THE OHIO SECRETARY OF STATE. ***

OHIO SECRETARY OF STATE, CORPORATE RECORD

NAME: ORBITRON INDUSTRIES, INC.

TYPE: DOMESTIC FOR PROFIT CORPORATION

STATUS: NOT IN GOOD STANDING

DATE OF INCORPORATION/QUALIFICATION: 11/13/1985

MAILING ADDRESS: CRANE TOWNSHIP

COUNTY OF PRINCIPAL OFFICE: WYANDOT

REGISTERED AGENT: OHIO STATUTORY SERVICES, INC

REGISTERED OFFICE: 22 N MAIN ST
KENTON
43326

INCORPORATORS: RALPH RINGELMAN, KENNETH E WESSLER, JOHN M TUDOR

CHARTER NUMBER: 666088

CAPITAL/STOCK: \$ 0 2700 NO PAR COMMON

HISTORY:

DATE FRAME	TRANSACTION	ROLL
-----	-----	-----
08/01/1986 1020	DOMESTIC/DISSOLUTION	F990
11/13/1985 0494	DOMESTIC ARTICLES/FOR PROFIT CORPORATION	F779

* ENTER LEXDOC TO ORDER A CERTIFICATE OF GOOD STANDING OR OTHER DOCUMENTS *

PAGE 4

LEVEL 1 - 3 OF 3 DOCUMENTS

*** THIS DATA IS FOR INFORMATION PURPOSES ONLY. CERTIFICATION CAN ONLY BE OBTAINED THROUGH THE OFFICE OF THE OHIO SECRETARY OF STATE. ***

OHIO SECRETARY OF STATE, CORPORATE RECORD

NAME: ORBITRON INDUSTRIES INC

TYPE: FOREIGN FOR PROFIT LICENSE

STATUS: IN GOOD STANDING

DATE OF INCORPORATION/QUALIFICATION: 06/26/1986

MAILING ADDRESS: 1100 W BEARDSLEY AVE , ELKHART, IN 46514

STATE OF INCORPORATION: INDIANA

REGISTERED AGENT: STEVEN MOORE

REGISTERED OFFICE: 901 S MAIN ST
DELPHOS
45833

CHARTER NUMBER: 680503

CAPITAL/STOCK: 1500 (shares allocated to Ohio)

HISTORY:

DATE FRAME	TRANSACTION	ROLL
05/18/1990 1741	FOREIGN/REINSTATEMENT	G865
	FOREIGN/AGENT SUBSEQUENT APPOINTMENT '88 FORM 7, NO FEE ASSESSED '89 FORM 7, NO FEE ASSESSED '90 FORM 7, NO FEE ASSESSED FOREIGN/CHANGE OF PRINCIPAL OFFICE OUTSIDE OHIO CANCELLED FOREIGN CORPORATION FOR FAILURE TO FILE AND/OR PAY FEE(S) ON FORM 7	G822
03/02/1990 1839	ORBITRON INDUSTRIES INC. '87 FORM 7, FEE ASSESSED	G210
07/23/1987 1537	FOREIGN LICENSE/FOR PROFIT	F942
06/26/1986 0394		

*** ENTER LEXDOC TO ORDER A CERTIFICATE OF GOOD STANDING OR OTHER DOCUMENTS ***

****-----
-----****

* 5 PAGES 111 LINES
*
* 1:03 P.M. STARTED 1:04 P.M. ENDED
*

****-----
-----****
****-----
-----****

*		EEEEEE	N	N	DDDD
	*				
*		E	N	N	D D
	*				
*		E	NN	N	D D
	*				
*		EEE	N N N		D D
	*				
*		E	N NN		D D
	*				
*		E	N N		D D
	*				
*		EEEEEE	N	N	DDDD
	*				

****-----
-----****

****-----
-----****

**SEND TO: CHABRIA, MONESH
ENVIRONMENTAL PROTECTION AGENCY-CHICAGO
OFFICE OF REGIONAL COUNSEL
77 W JACKSON BLVD MAIL CODE C-3T
CHICAGO, ILLINOIS 60604**

Table 1

WASTE DISPOSAL SUMMARY

Hazardous Material	Quantity	Manifest #	Disposal Facility
RQ Hazardous Waste Liquid, NOS (Cd, Pb) 9, NA 3082 PG III (D006, D008)	60 drums (3300 gal)	3469922	Envotech Belleville, MI
RQ Waste Paint Related Material 3, UN 1263 PG II (D001)	50 drums (2750 gal)	3469988	Petro-Chem Processing Detroit, MI
RQ Waste Corrosive Liquids, NOS (Na, KOH) 8, UN 1760 PG I (D002)	2 drums (110 gal)	3469921	Chem-Met Services Wyandotte, MI
Waste Sodium Nitrate UN 1198 PG III (D001)	1 drum (55 gal)	3469921	Chem-Met Services Wyandotte, MI
MT drums	104 drums	N/A	Columbus Steel Drum Pontiac, MI
Oil and Water Non-hazardous	41 drums (1905 gal)	00003	Cousins Waste Control/BBC Toledo, OH
RQ Waste Corrosive Liquids, NOS (D002) 8, UN 1760 PG I	3 drums (86 gal)	3469782	Chem-Met Services Wyandotte, MI

7/7/95